

CHIRP - Feature # 9997

Status:	Closed	Priority:	Normal
Author:	Jim Unroe	Category:	
Created:	08/21/2022	Assignee:	Jim Unroe
Updated:	08/23/2022	Due date:	
Chirp Version:	daily		
Model affected:	RT21 and others		
Subject:	Driver Maintenance: retevis_rt21.py		
Description	Improvement for Retevis RB17A, RB26, RT21 and RT76. The driver should default to Power = High when permitted. Jim KC9HI		

Associated revisions

Revision 3731:ba9a27f233d6 - 08/23/2022 12:29 am - Jim Unroe

Driver Maintenance: Default to High Power Level

This patch sets the default Power level when programming a memory to High.

Retevis RB17A, RB26, RT21 and RT76

fixes #9997

History

#1 - 08/21/2022 10:01 pm - Jim Unroe

- Status changed from *In Progress* to *Resolved*
- % Done changed from 0 to 100

A patch has been submitted. Support will be in the next CHIRP daily build following acceptance.

Jim KC9HI

#2 - 08/23/2022 12:53 am - Anonymous

- Status changed from *Resolved* to *Closed*

Applied in changeset commit:ba9a27f233d6.