

CHIRP - Feature # 9998

Status:	Closed	Priority:	Normal
Author:	Jim Unroe	Category:	
Created:	08/21/2022	Assignee:	Jim Unroe
Updated:	08/23/2022	Due date:	
Chirp Version:	daily		
Model affected:	RT21 and others		
Subject:	Driver Maintenance: retevis_rt21.py		
Description	<p>Improvement for Retevis RB17A, RB26, RT21 and RT76. The driver should default to Mode = FM when permitted.</p> <p>Jim KC9HI</p>		

Associated revisions

Revision 3732:027710c3ed6a - 08/23/2022 12:29 am - Jim Unroe

Driver Maintenance: Default to Wide Bandwidth

This patch sets the default Mode when programming a memory to FM.

Retevis RB17A, RB26, RT21 and RT76

Fixes #9998

History

#1 - 08/21/2022 10:02 pm - Jim Unroe

- Status changed from *In Progress* to *Resolved*
- % Done changed from 0 to 100

A patch has been submitted. Support will be in the next CHIRP daily build following acceptance.

Jim KC9HI

#2 - 08/23/2022 12:53 am - Anonymous

- Status changed from *Resolved* to *Closed*

Applied in changeset commit:027710c3ed6a.