

CHIRP - New Model # 1229

Status:	Closed	Priority:	Normal
Author:	Ed McKinney	Category:	
Created:	11/09/2013	Assignee:	
Updated:	02/18/2020	Due date:	
Chirp Version:	daily		
Equipment Loan Offered:	No		
Subject:	Yaesu FT-8100		
Description			
<p>Hello</p> <p>I have several Yaesu FT-8100 model radio.</p> <p>However, the software I have only works in MS-DOS 6.22, but not in windows.</p> <p>What would it take for you nice folks to acquire and add a windows version to CHIRP abilities?</p> <p>I and others in my region will appreciate the add.</p> <p>Thanks in advance</p> <p>Ed --- KB8QEU</p>			
Related issues:			
duplicates New Model # 1467: Yaesu FT-8100R		Closed	02/27/2014

Associated revisions

Revision 2573:0ff0c756e192 - 06/14/2015 08:00 pm - Eric Allen

Fix PEP8 failures due to line length in FT-8100 driver

Related to #1229

History

#1 - 11/11/2013 08:04 am - Jens Jensen

are you able to run this in DOSBox within windows?

<http://www.dosbox.com/information.php?page=0>

#2 - 01/15/2015 08:27 am - Eric Wolak

Hi Ed,

I just picked up an FT-8100 and a programming cable, so I'm going to take a crack at getting it working in CHIRP. I think I've found a copy of ADMS-2D to work from, and I'll take a shot at it this weekend.

#3 - 02/18/2020 03:24 pm - Bernhard Hailer

- *Tracker changed from Bug to New Model*
- *Subject changed from To add Yaesu FT-8100 to the programming ability listing. to Yaesu FT-8100*
- *Status changed from New to Closed*
- *Assignee deleted (Ed McKinney)*
- *Target version set to chirp-daily*
- *Chirp Version changed from 0.3.0 to daily*
- *Equipment Loan Offered set to No*

Duplicates #1467, which has some comments.