

CHIRP - New Model # 1793

Status:	Feedback	Priority:	Normal
Author:	Gerardo Gerardo	Category:	
Created:	07/27/2014	Assignee:	
Updated:	06/25/2020	Due date:	
Chirp Version:	daily		
Equipment Loan Offered:	No		
Subject:	Polmar Work		
Description			
<p>Hi, i've this radio Polmar Work. It's very similar to Baofeng 888, in fact if i try to read with Chirp selecting Baofeng 888 the reading is succesful, but if i try to write the radio i get this error "Failed to send block to radio at 03d8". If i try to read again chirp write with success the frequencies but not the setting. In fact if i try to power on the radio the language is chinese and for each channel I can only hear a beep infinite.</p> <p>Thanks</p>			

History

#1 - 06/25/2020 05:04 pm - Bernhard Hailer

- Status changed from New to Feedback
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily

Does any of the other Baofeng drivers work, and perhaps give better results? Thanks!