

CHIRP - Bug # 1801

Status:	Closed	Priority:	Normal
Author:	Tyler Tidman	Category:	
Created:	08/01/2014	Assignee:	Tyler Tidman
Updated:	08/19/2014	Due date:	
Chirp Version:	daily		
Model affected:	(All models)		
Platform:	All		
Subject:	Stock config has offset for 6m FM calling frequency		
Description	<p>Installed chirp-daily from ppa (20140724~trusty~1, Ubuntu 14.04.1 LTS amd64)</p> <p>The 6m FM calling frequency in the US Calling Frequencies.csv file has a negative duplex value set.</p> <p>To recreate the issue: Select the "open stock config" from the file menu and load the "US calling frequencies" csv file. Look at the duplex column on the row with the 52.525000 entry (channel 1).</p> <p>Problem summary: Duplex value set here should be "(None)" with offset 0.000000 just like the other 2m, 1.25m and 70cm FM calling frequencies.</p> <p>(NOTE: These FM calling frequencies are used in Canada as well as the US. There are also typically other standard calling frequencies used for other modes such as SSB, CW, AM, etc.)</p>		

Associated revisions

Revision 2241:424916a7f717 - 08/03/2014 07:16 pm - Tyler Tidman

[All] Remove offset for 6m FM calling freq in stock config, fixes #1801

History

#1 - 08/01/2014 01:59 pm - Tyler Tidman

Confirmed that this is error is still present after doing a fresh hg clone.

#2 - 08/01/2014 02:29 pm - Tyler Tidman

A patch has been submitted.

#3 - 08/19/2014 03:01 pm - Tom Hayward

- Status changed from New to Closed

- Assignee set to Tyler Tidman

- Target version set to 0.4.1

- % Done changed from 0 to 100