

CHIRP - New Model # 1879

Status:	New	Priority:	Normal
Author:	Richard Carlone	Category:	
Created:	08/30/2014	Assignee:	
Updated:	02/24/2020	Due date:	
Chirp Version:	daily		
Equipment Loan Offered:	No		
Subject:	Tonfa TF-Q5		
Description	Tonfa TF-Q5 transceiver not recognized.		

History

#1 - 02/24/2020 05:06 pm - Bernhard Hailer

- Tracker changed from Bug to New Model
- Subject changed from Tonfa TF-Q5 transceiver not recognized. to Tonfa TF-Q5
- Description updated
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Equipment Loan Offered set to No

This isn't a bug - this radio is simply not (yet) supported.

The addition of a new radio to Chirp requires two things:

- 1) a volunteer developer who takes the task to work on this driver,
- 2) availability of test equipment, such as a loaner radio (see [\[\[Rules For Loaning A Radio\]\]](#)).

Unfortunately, you need to wait until both conditions have been met.