

CHIRP - New Model # 2471

Status:	Rejected	Priority:	Normal
Author:	Neil Tideswell	Category:	
Created:	03/30/2015	Assignee:	
Updated:	03/30/2015	Due date:	
Chirp Version:	0.4.0		
Equipment Loan Offered:	No		
Subject:	New model request		
Description	I have a new model request for the Baofeng 997-S the firmware version is BFS297		

History

#1 - 03/30/2015 02:50 pm - Jim Unroe

- Status changed from New to Rejected

This is just another [Baofeng UV-5R variant](#) and is already supported.

Jim KC9HI

#2 - 03/30/2015 07:27 pm - Neil Tideswell

Jim Unroe wrote:

This is just another [Baofeng UV-5R variant](#) and is already supported.

Jim KC9HI

It maybe a UV-5R variant but it's firmare is BFS297 and chirp does not work I have tried with this variant, however My UV-5R with firmware BFB297 does work perhaps therefore you would be so kind as to give it a second look instead of just assuming P.S. my friend has a baofeng 997-S aswell but his firmware is BFN297 his does work with chirp