

## CHIRP - Bug # 2773

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Gabor Mentes	<b>Category:</b>	
<b>Created:</b>	08/02/2015	<b>Assignee:</b>	
<b>Updated:</b>	04/28/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	Yaesu FT-60		
<b>Platform:</b>	Windows		
<b>Subject:</b>	Yaesu FT-60 upload		
<b>Description</b>			
<p>Hi ! I tired many times with 3 different cable. This is what I got. I can download the radio, but I can not upload . The same thing is working with out any problem with my Baofeng BF-F8HP.</p> <p>Thanks for the help. AA5MG</p> <p>Gabor Mentes</p> <p>73</p>			

### History

#### #1 - 02/29/2020 06:58 pm - Bernhard Hailer

- Tracker changed from Feature to Bug
- Subject changed from Yeasu FT60 upload to Yaesu FT-60 upload
- Status changed from New to Feedback
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected changed from (All models) to Yaesu FT-60
- Platform set to Windows

Please provide a debug log as described in "[[How To Report Issues]]". Thanks!

#### #2 - 04/28/2020 02:09 pm - Bernhard Hailer

- Status changed from Feedback to Closed

No more feedback by submitter.