

CHIRP - Bug # 3115

Status:	Closed	Priority:	Normal
Author:	Kevin Fitz-Gerald	Category:	
Created:	01/01/2016	Assignee:	
Updated:	04/23/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng UV-82HP		
Platform:	Windows		
Subject:	Baofeng UV82HP not recognized but no error message		
Description			
Windows 10 Chirp daily 20150814 Baofeng UV-82HP Prolific 3.2.0.0 (looks good in Device Manager) I start Chirp and I can't see the radio. I click Download from Radio and nothing happens. I open a stock configuration and Upload to Radio is greyed out. No error messages. Just nothing. It worked on this computer in the past, prior to a September reformat and OS reinstall.			

History

#1 - 01/29/2020 05:19 pm - Bernhard Hailer

- Status changed from New to Feedback
- Target version set to chirp-daily
- Model affected changed from (All models) to Baofeng UV-82HP

Have you been able to resolve this on your own since you submitted this?

If you haven't, and if you're still having this issue, please refer to the Wiki [\[\[How To Report Issues\]\]](#), and provide a debug log. Thanks!

#2 - 04/23/2020 04:25 pm - Bernhard Hailer

- Status changed from Feedback to Closed

No more feedback by submitter.