

CHIRP - Bug # 3157

Status:	Closed	Priority:	Normal
Author:	David Dallessandro	Category:	
Created:	01/12/2016	Assignee:	
Updated:	04/23/2020	Due date:	
Chirp Version:	daily		
Model affected:	Wouxun UV-3D		
Platform:	Windows		
Subject:	Wouxun UV-3D programming issue		
Description	Recently i programmed the radio via chirp and now the pf1 radio doesnt work and cant make outbound and cant rcve any transmissions even with correct pl and offsets need help please		

History

#1 - 01/27/2020 05:26 pm - Bernhard Hailer

- Subject changed from UV3d to Wouxun UV-3D programming issue
- Status changed from New to Feedback
- Assignee deleted (David Dallessandro)
- Priority changed from Urgent to Normal
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected changed from wouxun uv3d to Wouxun UV-3D

Sorry for the late response (and maybe you were able to resolve this already). I'm unsure what you did here. The .csv file you attached is not a CSV file, it's something binary (CSV is a pure text format) - what did you do with this file? I'm also unsure what you can do here. If the radio supports a factory reset, I would try that.

#2 - 04/23/2020 05:09 pm - Bernhard Hailer

- Status changed from Feedback to Closed

No more feedback by submitter.

Files

kb2vvd.csv	8 kB	01/12/2016	David Dallessandro
------------	------	------------	--------------------