

CHIRP - Bug # 3207

Status:	Closed	Priority:	Normal
Author:	Steve Benfield	Category:	
Created:	01/23/2016	Assignee:	
Updated:	04/23/2020	Due date:	
Chirp Version:	daily		
Model affected:	UV-5R HERO		
Platform:	Windows		
Subject:	frequency is out of range		
Description			
<p>I have a Baofeng UV-5R and cannot use CHIRP to program any 70cm frequencies, I get an error saying the frequency is out of range. These frequencies were in my radio before using CHIRP so I know the radio will support them. I have CHIRP version CHIRP daily-20151020. Any help or suggestions?</p>			

History

#1 - 01/23/2016 12:42 pm - Jim Unroe

- Status changed from New to Feedback

Sounds like you either have a VHF/220 radio or you have a VHF/UHF radio that is identifying with an invalid "ident". So CHIRP is detecting your radio as a VHF/220 radio (can you key in 220 MHz frequencies?).

What is your firmware version (Settings -> Other Settings -> Firmware Message 1: and Firmware Message 2:)? The firmware version can reveal the true ability of your radio.

If it a matter of an invalid "ident", you can "fix" this with the OEM VIP software. Or you can make a fresh download, save it as a CHIRP Radio Images (*.img) file and email it to me (click my name for the email address). I will be able to determine what type of radio you have and advise you about what to do next.

Jim KC9HI

#2 - 04/23/2020 05:37 pm - Bernhard Hailer

- Status changed from Feedback to Closed

- Assignee deleted (Steve Benfield)

- Priority changed from High to Normal

No more feedback by submitter.