

CHIRP - Feature # 3291

Status:	Feedback	Priority:	Normal
Author:	Jose Cruz	Category:	
Created:	02/06/2016	Assignee:	
Updated:	01/27/2020	Due date:	
Chirp Version:	daily		
Model affected:	Jetstream JT-370M		
Subject:	Jetstream JT-370M - individual ID setting		
Description	<p>I need a way to change the transceiver's individual id. All come out with id 1000 by default, but in order to use individual call or group code each unit needs a different code. This item can't be changed manually only through software.</p>		

History

#1 - 02/06/2016 12:04 pm - Jose Cruz

This should have been a feature request.

#2 - 02/06/2016 04:29 pm - Jose Cruz

Sorry this my first time. This issue is with Linux on the Raspberry PI.

#3 - 01/27/2020 05:19 pm - Bernhard Hailer

- Tracker changed from Bug to Feature
- Subject changed from JT370M Jetstream to Jetstream JT-370M - individual ID setting
- Status changed from New to Feedback
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected changed from (All models) to Jetstream JT-370M

Does a newer version of Chirp help? Thanks.