

## CHIRP - New Model # 3879

|                                |                                      |                  |        |
|--------------------------------|--------------------------------------|------------------|--------|
| <b>Status:</b>                 | Feedback                             | <b>Priority:</b> | Normal |
| <b>Author:</b>                 | Che saiful amri bin che mahtar Ayie  | <b>Category:</b> |        |
| <b>Created:</b>                | 08/03/2016                           | <b>Assignee:</b> |        |
| <b>Updated:</b>                | 02/02/2020                           | <b>Due date:</b> |        |
| <b>Chirp Version:</b>          | daily                                |                  |        |
| <b>Equipment Loan Offered:</b> | No                                   |                  |        |
| <b>Subject:</b>                | Kenwood TK-2307                      |                  |        |
| <b>Description</b>             | (Submitter did not add any comment.) |                  |        |

### History

#### #1 - 02/02/2020 08:43 pm - Bernhard Hailer

- Tracker changed from Bug to New Model
- Subject changed from Tk 2307 kenwood to Kenwood TK-2307
- Description updated
- Status changed from New to Feedback
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Equipment Loan Offered set to No