

## CHIRP - New Model # 4299

<b>Status:</b>	New	<b>Priority:</b>	Normal
<b>Author:</b>	Doychin Donchev	<b>Category:</b>	
<b>Created:</b>	12/11/2016	<b>Assignee:</b>	
<b>Updated:</b>	04/20/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Equipment Loan Offered:</b>	No		
<b>Subject:</b>	Crony CN810		
<b>Description</b>			
<p>I got this one Crony cn-810 16 channel but can not program it with any of the similar one. This is how it look -&gt; <a href="http://funsouq.hzit.ae/product.php?id=10357ln">http://funsouq.hzit.ae/product.php?id=10357ln</a> difference to the other kenwood clones this one have a single jack programming cable. Most of the models with 16 channels have a separate switch when here it is below the volume knob. Just hoping for some advice? Thank you.</p>			

### History

#### #1 - 04/20/2020 10:56 pm - Bernhard Hailer

- Tracker changed from Bug to New Model
- Subject changed from Crony-cn810 incompatibility(New model) to Crony CN810
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Equipment Loan Offered set to No

Not a bug - this is a New Model request.