

CHIRP - Bug # 4301

Status:	Closed	Priority:	Normal
Author:	Samuel Poissant	Category:	
Created:	12/12/2016	Assignee:	
Updated:	04/20/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng UV82HP		
Platform:	Windows		
Subject:	Radio refused to communicate with Chirp		
Description			
<p>Hy I have a Baofeng UV82HP and a ftdi cable and when I try to connect my radio with chirp on a windows machine it tells me (Radio refused to send block 0x1ec0) and I cant talk with the radio.</p> <p>Chirp build CHIRP daily-20161208</p>			
Related issues:			
duplicates Bug # 5837: Radio Did Not Respond Error.		Closed	05/30/2018

History

#1 - 04/20/2020 07:28 pm - Bernhard Hailer

- Status changed from New to Closed

Duplicates many other tickets. Please use #5837 for further inquiries.