

CHIRP - Feature # 435

Status:	Closed	Priority:	Normal
Author:	Filippi Marco	Category:	
Created:	01/17/2013	Assignee:	Filippi Marco
Updated:	02/03/2013	Due date:	
Chirp Version:	daily		
Model affected:	FT817		
Subject:	FT817 add support for radio settings		
Description			

Associated revisions

Revision 1824:3d590bbff66d - 01/17/2013 08:22 am - Filippi Marco

[ft817] Settings support
implement #435

Revision 1825:ffdc96d1f505 - 01/20/2013 10:35 am - Filippi Marco

[ft817] Add CW id setting
addition to #435

Revision 1830:d4be9794e137 - 02/03/2013 09:42 pm - Filippi Marco

[ft817] Add front panel settings
last part of #435

Revision 1860:20551bfe9604 - 02/11/2013 08:44 am - Filippi Marco

[ft817NDus] Settings tab was broken
I'm sure I had tested it but ...
related to #435

Revision 1861:23d090b0756c - 02/11/2013 08:44 am - Filippi Marco

[ft817NDus] Settings tab was broken
I'm sure I had tested it but ...
related to #435

Revision 1937:13cbf492ce5a - 03/30/2013 10:59 am - Filippi Marco

[ft817] Correct some cut&past typo in settings
related to #435

History

#1 - 02/03/2013 01:48 pm - Filippi Marco

- Status changed from New to Closed

Last settings have been implemented and will be in next days daily build