

## CHIRP - Bug # 4633

<b>Status:</b>	Feedback	<b>Priority:</b>	Normal
<b>Author:</b>	RANDY CAMILOTES	<b>Category:</b>	
<b>Created:</b>	03/16/2017	<b>Assignee:</b>	Jim Unroe
<b>Updated:</b>	03/27/2017	<b>Due date:</b>	
<b>Chirp Version:</b>	0.4.0		
<b>Model affected:</b>	(All models)		
<b>Platform:</b>	Windows		
<b>Subject:</b>	UV-6R Incomplete Cloning Progress		
<b>Description</b>			
Attached is the img file of the programming of my baofeng uv-6r radio.			
It seems to not be able to completely finish its cloning progress. thank you.			

### History

#### #1 - 03/16/2017 03:50 pm - Jim Unroe

- Status changed from New to Feedback

Explain what you mean by "not able to completely finish"? Please, include a debug.log file.

Jim

#### #2 - 03/21/2017 06:33 pm - RANDY CAMILOTES

- File debug.log added

The cloning progress display "with the green bar" doesn't completely reach the end of the bar

#### #3 - 03/22/2017 03:40 am - Jim Unroe

For the upload? It goes to about 3 quarters and jumps ahead. If there are no errors reported, this is normal.

The downloaded image looks complete. I don't know why CHIRP doesn't detect it though.

The debug.log is "clean" and does not contain any cloning operation.

Launch CHIRP

Cause the error

Close CHIRP

Grab the debug.log file.

Jim

#### #4 - 03/27/2017 03:03 am - RANDY CAMILOTES

tHANKS FOR the update Jim,

It can't seem to upload the new message that i assign whenever the radio is turned on...it just continues to show "WELCOME" even if i have already changed it to something else. is this a radio limitation issue?

**#5 - 03/27/2017 03:29 am - Jim Unroe**

Maybe, maybe not. Attach your edited image plus a freshly downloaded image from your radio.

Jim KC9HI

**Files**

---

Baofeng_UV-6R_20170312 BUG IMAGE FILE.img	8 kB	03/16/2017	RANDY CAMILOTES
debug.log	19.1 kB	03/21/2017	RANDY CAMILOTES