

## CHIRP - New Model # 4645

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Tibor Finta	<b>Category:</b>	
<b>Created:</b>	03/19/2017	<b>Assignee:</b>	
<b>Updated:</b>	03/24/2018	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Equipment Loan Offered:</b>	No		
<b>Subject:</b>	Baojie BJ-218		
<b>Description</b>	I need if the CHIRP support the Baojie BJ-218 transceiver...		

### Associated revisions

Revision 2965:96bc56916c95 - 03/20/2018 06:38 pm - Jim Unroe

[LT725UV] Add support for Baojie BJ-218 and clones.

This patch adds support for Baojie BJ-218 and clones.  
It also adds VFO, DTMF and miscellaneous other settings

Applies to fixes #5595, #5407 and #4645

### History

**#1 - 03/19/2017 11:10 am - Tim Smith**

- Subject changed from Support to Baojie BJ-218

**#2 - 08/15/2017 04:17 pm - Hal Hostetler**

The BJ-218 is identical to the Luiton LT-725UV and its CHIRP driver works just fine, I have one of each, factory software and files are the same, CHIRP .img files are interchangeable.

Hal WA7BGX

**#3 - 03/24/2018 12:54 pm - Rick DeWitt**

- Status changed from New to Closed