

## CHIRP - Bug # 5337

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Andrew DePratti	<b>Category:</b>	
<b>Created:</b>	11/12/2017	<b>Assignee:</b>	
<b>Updated:</b>	09/09/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	(All models)		
<b>Platform:</b>	MacOS		
<b>Subject:</b>	MAC DRIVER FOR OS X Yosemite Arduinos with CH340		
<b>Description</b>			
<p>Hi all,</p> <p>After much time and efforts. I finally found a Mac driver that works with the knock programming cables. Below is link for those interested.</p> <p><a href="https://0xcf.com/2015/03/13/chinese-arduinios-with-ch340-ch341-serial-usb-chip-on-os-x-yosemite/">https://0xcf.com/2015/03/13/chinese-arduinios-with-ch340-ch341-serial-usb-chip-on-os-x-yosemite/</a></p> <p>Good Luck!</p>			

### History

#### #1 - 03/04/2020 02:45 pm - Bernhard Hailer

- Subject changed from MAC DRIVER FOR OS X Yosemite Arduinos with CH340 to MAC DRIVER FOR OS X Yosemite Arduinos with CH340
- Status changed from New to Blocked
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily

Keeping open until we add this to the Wiki.

#### #2 - 09/09/2020 04:31 pm - Bernhard Hailer

- Status changed from Blocked to Closed

Link does no longer work :-(