

CHIRP - Bug # 5409

Status:	New	Priority:	Normal
Author:	Richard Neese	Category:	
Created:	12/02/2017	Assignee:	Richard Neese
Updated:	12/02/2017	Due date:	
Chirp Version:	0.4.0		
Model affected:	(All models)		
Platform:	Windows		
Subject:	fmn/fmw setting		
Description	the narrow wide fm setting is setting to narrow by default even when set to narrow its not setting to wide when set to FM		

History
