

## CHIRP - New Model # 5433

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Gilles Rosenkranz	<b>Category:</b>	
<b>Created:</b>	12/09/2017	<b>Assignee:</b>	
<b>Updated:</b>	01/27/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Equipment Loan Offered:</b>	No		
<b>Subject:</b>	Baofeng UV-8D		
<b>Description</b>			
Hello I can't connect my UV-8D...			
It working fine with the Baofeng UV_8 program but Chirp won't: "No response from radio"			
Can I trying something?			
<b>Related issues:</b>			
duplicates New Model # 4519: Baofeng / Pofung UV-8d		<b>Closed</b>	<b>02/12/2017</b>

### History

#### #1 - 12/09/2017 08:10 pm - Jim Unroe

- Status changed from New to Feedback

The Baofeng UV-8D model is not supported by CHIRP

Jim KC9HI

#### #2 - 01/27/2020 03:01 pm - Bernhard Hailer

- Tracker changed from Feature to New Model
- Subject changed from UV-8D to Baofeng UV-8D
- Status changed from Feedback to Closed
- Assignee deleted (Aaron P)
- Priority changed from High to Normal
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Equipment Loan Offered set to No

This model is currently unsupported; I made this a New Model request; however, it duplicates #4519.