

CHIRP - Bug # 5535

Status:	Closed	Priority:	Normal
Author:	Joel S	Category:	
Created:	01/28/2018	Assignee:	
Updated:	07/04/2020	Due date:	
Chirp Version:	daily		
Model affected:	Yaesu FT-8800		
Platform:	Windows		
Subject:	Yaesu FT-8800 -- Right Memory Bank is not working at all		
Description	<p>Chirp is not handling Right Memory bank correctly. It is showing what is in the left bank visually in the app, but nothing is properly being read or written to the actual Right memory banks.</p>		

History

#1 - 02/04/2018 03:19 pm - Joel S

Issues remains in 02042018 daily.

#2 - 01/22/2020 11:52 am - Bernhard Hailer

- Status changed from New to Closed
- Priority changed from High to Normal
- Target version set to chirp-daily

Duplicate of #1965. Please add further feedback there. Thanks!

#3 - 07/04/2020 06:57 pm - Joel S

Bernhard Hailer wrote:

| Duplicate of #1965. Please add further feedback there. Thanks!

May I ask why this was closed? The issue remains.

#4 - 07/04/2020 06:57 pm - Joel S

B

#5 - 07/04/2020 07:00 pm - Joel S

Oops, ignore, ad block was hiding some content. I see that there is another issue, so this one was closed. I'll follow the other one. Thanks.