

CHIRP - Bug # 5595

Status:	Closed	Priority:	Normal
Author:	Rick DeWitt	Category:	
Created:	02/19/2018	Assignee:	Rick DeWitt
Updated:	03/18/2019	Due date:	02/22/2018
Chirp Version:	daily		
Model affected:	(All models)		
Platform:	Windows		
Subject:	Baojie BJ-218 and Aliases		
Description	<p>I have modified the original Luiton lt725uv.py driver to provide full dual-vfo Settings support as well as DTC cross-modes. I believe that the Baojie BJ-218 is actually the parent radio, so I have added the following aliases-</p> <p>Luiton LT-725Uv (Perhaps that original driver should be removed..??)</p> <p>Zastone BJ-218</p> <p>Hesenate BJ-218</p> <p>Only High and Low power modes can be set via software (1 bit in memory), even though some clones have three power levels.</p> <p>This driver is almost for submission; in final testing..</p>		

Associated revisions

Revision 2965:96bc56916c95 - 03/20/2018 06:38 pm - Jim Unroe

[LT725UV] Add support for Baojie BJ-218 and clones.

This patch adds support for Baojie BJ-218 and clones.
It also adds VFO, DTMF and miscellaneous other settings

Applies to fixes #5595, #5407 and #4645

History

#1 - 03/18/2019 10:01 am - Rick DeWitt

- Status changed from New to Closed
- Chirp Version changed from 0.4.0 to daily

Files

baojie_bj218.py	46.2 kB	02/19/2018	Rick DeWitt
-----------------	---------	------------	-------------