

CHIRP - New Model # 5609

Status:	Closed	Priority:	Normal
Author:	Matthew Smith	Category:	
Created:	02/26/2018	Assignee:	
Updated:	03/06/2020	Due date:	
Chirp Version:	daily		
Equipment Loan Offered:	Yes		
Subject:	Anytone 778UV		
Description	Please someone add this radio. The quality is amazing, the screen is amazing and the audio is amazing but programming is the worst of any Chinese radio I have used and the factory software isn't much better. Chirp has spoiled me and this radio is in desperate need of it.		
Related issues:	duplicates New Model # 4901: Anytone At-778UV Closed 06/12/2017		

History

#1 - 03/11/2019 08:03 am - Derek Haden

This is also the same rig as the Retevis RT95 and CRT Micron.

There are 3 issue tickets open for this

#5609 (this one)

#6003

#6425

I don't know how to move this forward? I am happy to assist in investigating this transceiver.

But do not know what is required, or where to discover what is required?

#2 - 10/12/2019 08:56 pm - Danny Burdick

Not a developer

Control languages hacker

Years of breaking/stumbling across "the one thing that made it work"

I have an Anytone 778UV

Run Debian Stretch 9

Have their windows software running very well under wine but like everyone else

no ttyusb0 to comX communication...

Can spend many nights beating on a concept in code...

tnx

#3 - 01/18/2020 01:36 pm - Bernhard Hailer

- Status changed from New to Closed

- Target version set to chirp-daily

- Chirp Version changed from 0.4.0 to daily

Request already submitted before; see #4901.

#4 - 03/06/2020 11:02 am - Bernhard Hailer

@Danny Burdick, you might want to read the Wiki article "[[Developers]]". Perhaps we'll see you there?