

CHIRP - Bug # 6185

Status:	Feedback	Priority:	Normal
Author:	Pavel Milanes	Category:	
Created:	10/23/2018	Assignee:	Pavel Milanes
Updated:	05/11/2020	Due date:	
Chirp Version:	daily		
Model affected:	Wouxun KG-UV1DP/UV2D/UV3D		
Platform:	All		
Subject:	Wouxun KG-UV1DP/UV2D/UV3D need separate entries in the model list.		
Description	<p>In the supported radio page we read that the Wuoxun models KG-UV1DP, KG-UV2D & KG-UV3D are supported, but they have not a individual entry on the model list one you select the Wuoxun OEM.</p> <p>This is easily fixed by using the aliasing for radio clones.</p> <p>This issue is to test and patch that.</p>		
Related issues:	duplicated by Bug # 5613: WOUXUN KG-UV3D Radio not in list, MAC OS10.13.3. Hi... Closed 02/28/2018		

History

#1 - 10/23/2018 02:20 pm - Pavel Milanes

- Status changed from New to Feedback

I'm working on this.

Changes are easy but I need a few images with Chirp of the related radios to confirm that the changes are working.

Needed ones are:

- Wuoxun KG-UV1DP
- Wuoxun KG-UV2D
- Wuoxun KG-UV3D

I need at least two different ones to validate the changes.

Cheers, Pavel CO7WT.

#2 - 05/11/2020 09:19 pm - Bernhard Hailer

- Subject changed from Wuoxun KG-UV1DP/UV2D/UV3D need an entry own entry on the model list. to Wuoxun KG-UV1DP/UV2D/UV3D need separate entries in the model list.

- Model affected changed from Wuoxun KG-UV1DP/UV2D/UV3D to Wuoxun KG-UV1DP/UV2D/UV3D

Hi Pavel, is this complete? Thanks!