

## CHIRP - Bug # 6189

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Kourosh Delpak	<b>Category:</b>	
<b>Created:</b>	10/23/2018	<b>Assignee:</b>	
<b>Updated:</b>	01/23/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	Baofeng UV-5R		
<b>Platform:</b>	Windows		
<b>Subject:</b>	Baofeng UV-5R UHF/VHF problem		
<b>Description</b>	<p>Hi Guys I Found Big Bug On Baofeng UV5R When The I Want Unlimited To UHF And VHF Its Limited When I Go On 390Mhz And Selected Menu I Saw Its Vhf This Is Big Problem and Because Of This Lower Than The 400Mhz Rx And Tx Very Poor Because It Use VHF Filters By The Way In VFO Mode When On dual Display Band Are UHF Frequencys The Up Is 390Mhz And The Down Freq Is 450Mhz For Example When Push Menu Buttum On VFO Mode Its Very Work PERFECT!!! And When The Signal Is Stop Its Go Uses VHF Fiteres But When Push Menu Buttum And See Menu 33 UHF And Push Over Moni Buttum It Stay And Uses UHF FILTER By The Way I Recive UHF SATCOM You Can Search And Watch My Video On Youtube(Kourosh Delpak) And Instagram (RadioFrequency.ep)</p> <p>Hope SOLVED This Bug</p> <p>Best Regards Kourosh Delpak EP2XX 73</p>		
<b>Related issues:</b>	duplicates Bug # 6187: Baofeng UV-5R UHF/VHF problem <b>Closed</b> <b>10/23/2018</b>		

### History

#### #1 - 01/23/2020 12:48 pm - Bernhard Hailer

- Subject changed from UHF/VHF to Baofeng UV-5R UHF/VHF problem
- Status changed from New to Closed
- Priority changed from Immediate to Normal
- Model affected changed from UV5R to Baofeng UV-5R

Duplicate of #6187