

CHIRP - Bug # 6439

Status:	Closed	Priority:	Normal
Author:	Alistair Burgess	Category:	
Created:	02/11/2019	Assignee:	
Updated:	05/12/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng GT-5TP		
Platform:	MacOS		
Subject:	Will not link to GT-5TP		
Description			
Trying to link to my GT-5TP keep getting Radio did not respond			
I have tried on Mac and Windows			

History

#1 - 02/20/2020 01:44 pm - Bernhard Hailer

- Status changed from New to Feedback
- Assignee deleted (Alistair Burgess)

Please review [\[\[How To Report Issues\]\]](#) and provide a debug log. Thanks!

#2 - 05/12/2020 08:48 pm - Bernhard Hailer

- Status changed from Feedback to Closed
- Target version set to chirp-daily
- Model affected changed from GT-5TP to Baofeng GT-5TP

No more feedback by submitter.