

CHIRP - Bug # 6821

Status:	Closed	Priority:	Normal
Author:	Jim Unroe	Category:	
Created:	05/30/2019	Assignee:	Jim Unroe
Updated:	05/14/2020	Due date:	
Chirp Version:	daily		
Model affected:	BTech GMRS-50X1		
Platform:	All		
Subject:	Problem selecting per-channel power levels in BTech GMRS-50X1		
Description	GMRS channels with the TX power level set to LOW power using the radio's menu system are displayed in CHIRP as being set to HIGH.		

Associated revisions

Revision 3231:bc8b50e0e189 - 05/30/2019 02:06 pm - Jim Unroe

[GMRS-50X1] Fix TX Power Level Setting Issue

This patch updates the "memory" structure to support 3 TX power levels.

#6821

History

#1 - 05/30/2019 07:09 am - Jim Unroe

- % Done changed from 0 to 100

A patch to correct the issue has been submitted.

Jim KC9HI

#2 - 05/14/2020 11:03 pm - Bernhard Hailer

- Status changed from In Progress to Closed

- Model affected changed from GMRS-50X1 to BTech GMRS-50X1

This appears to be complete.