

CHIRP - Bug # 6875

Status:	Rejected	Priority:	Normal
Author:	Nathan Bright	Category:	
Created:	06/20/2019	Assignee:	
Updated:	05/14/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng UV-5XP		
Platform:	Windows		
Subject:	New to CHIRP - Having issues		
Description			
Hello All,			
I seem to be having a common problem with programming a Baofeng. My UV-5XP allows me to pull data from it when i call it a UV5R but doesnt allow me to upload the data back into it citing a firmware issue. Its my understanding the software is working as designed but I simply dont know how to fix the issue. Any and All help is appreciated. I have attempted to upload the CHIRP file I want to upload to my radio if that helps in your prognosis.			
V/R			
Nathan KN4OVL			

History

#1 - 05/14/2020 11:31 pm - Bernhard Hailer

- Status changed from New to Rejected
- Target version set to chirp-daily
- Model affected changed from (All models) to Baofeng UV-5XP

If you're trying to upload the image of one radio into another, and that fails, then that other radio has a different firmware version than the first one. If the upload fails on the same radio you downloaded from, then that radio doesn't report its firmware version, and Chirp can't do the job.

The issue is that if Chirp uploads data to such a radio, it could potentially destroy it with data going into incorrect memory locations in the radio. To prevent this, Chirp refuses to write data if it can't determine whether it's ok to do so - it needs the firmware version first.

Therefore, this request must be rejected. Sorry :-(

Files

CHIRP.img	6.3 kB	06/20/2019	Nathan Bright
-----------	--------	------------	---------------