

CHIRP - Bug # 7189

Status:	Closed	Priority:	Normal
Author:	Erik Zalitis	Category:	
Created:	10/29/2019	Assignee:	
Updated:	02/01/2020	Due date:	
Chirp Version:	daily		
Model affected:	Yaesu FT-4XE		
Platform:	All		
Subject:	6.25 step not available on Yaesu FT-4XE		
Description	The European model of Yaesu FT-4X (FT-4XE) DOES allow for a 6.25 step in the frequency. Chirp, however, does not allow this step when saving the frequency in the table.		
Related issues:	duplicates Feature # 6619: Yaesu FT-65, 6.25 kHz stepping Closed 03/17/2019		

Associated revisions

Revision 3307:28fdc49d73f4 - 02/06/2020 05:42 am - Bernhard Hailer

[ft4] Add Yaesu FT-4XE. Fixes: #7189

This patch adds support for the Yaesu FT-4XE to Chirp. It offers an additional tune step of 6.25 kHz.

Revision 3311:394e5664ab91 - 02/06/2020 03:49 pm - Dan Smith

Add test images for FT-25R, FT-4VR, FT-4XE, FT-65E

Related to #7189, #6619, #7387, #7543

History

#1 - 01/27/2020 11:12 am - Bernhard Hailer

- Subject changed from 6.25 step not available on Yaesu FT-4X to 6.25 step not available on Yaesu FT-4XE
- Status changed from New to Feedback
- Target version set to chirp-daily
- Model affected changed from FT-4X to FT-4XE

Hello Erik, I would be very interested in getting an image of your FT-4XE. Any image would be fine, even one obtained right after a factory reset. I might then be able to fix the 6.25 kHz tune step problem.

#2 - 01/27/2020 11:17 am - Erik Zalitis

Hi Bernhard

I'll fix that, but I'm not sure what you mean with an image. Do you want me to dump the channels with Chirp and send you the results? That's not a problem. If you need something like a copy of the rom chips, I need some sort of guide on how to do that.

Regards, Erik.

#3 - 01/27/2020 11:37 am - Erik Zalitis

Ok. I'm a bit of a noob. Think I figured it out. Here's an image from the radio. It should be correct:

https://the.ericade.net/Files/Yaesu_FT-4XR_20191029.zip

#4 - 02/01/2020 02:34 pm - Bernhard Hailer

- *Status changed from Feedback to Closed*

- *Model affected changed from FT-4XE to Yaesu FT-4XE*

Thanks Erik! I'm working on a fix.

I'm closing this ticket, because it duplicates #6619. Please leave any further feedback there. Thanks!