

CHIRP - Bug # 7541

Status:	Closed	Priority:	Normal
Author:	Jake Bagwell	Category:	
Created:	01/08/2020	Assignee:	
Updated:	05/17/2020	Due date:	
Chirp Version:	daily		
Model affected:	Arcshell AR6		
Platform:	All		
Subject:	Error when trying to upload to Arcshell AR6		
Description			
<p>Using the newest version of Chirp, I am able to read the radio but not upload to it. I even tried uploading the stock config to it and it gave same error: "Failed to send block to radio at 0010"</p> <p>I have six of these radios that need to be programmed and they are all giving the same error</p> <p>*Chirp and cable work perfect on all of my Baofeng radios, tested those to rule out cable issue.</p>			

History

#1 - 04/19/2020 10:43 pm - Bernhard Hailer

- Status changed from New to Feedback
- Target version set to chirp-daily
- Platform changed from Windows to All

Could you please provide a debug log as described in the Wiki: "[[How To Report Issues]]"? Thanks!

#2 - 05/17/2020 05:33 pm - Bernhard Hailer

- Status changed from Feedback to Closed

No more feedback by submitter.