

## CHIRP - Bug # 7699

<b>Status:</b>	Feedback	<b>Priority:</b>	Low
<b>Author:</b>	Craig Jones	<b>Category:</b>	
<b>Created:</b>	03/12/2020	<b>Assignee:</b>	
<b>Updated:</b>	10/04/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	Anytone Driver		
<b>Platform:</b>	All		
<b>Subject:</b>	PowerWerx DB-750X tuning steps (patch attached)		
<b>Description</b>	<p>The PowerWerx DB-750X supports tuning steps of 2.5 and 12.5, but the anytone driver currently specifies only the default steps. See the attached patch file for what got me going. (While I was at it, I clarified the "Unsupported model" error to say "Unsupported model or bad connection".)</p> <p>NOTE: I tried to follow the instructions for submitting a soft-patch, but the "hg qnew" command didn't work for me. So, the patch file was created by "hg diff &gt; anyone.patch".</p>		

### History

#### #1 - 10/04/2020 12:52 pm - Bernhard Hailer

- Status changed from New to Feedback
- Target version set to chirp-daily
- Platform changed from Windows to All

Craig, please review the Wiki: [\[\[Developers\]\]](#) and submit your patch. In case of problems with Mercurial, please ask on the developers mailing list.  
Thanks!

### Files

anyone.patch	994 Bytes	03/12/2020	Craig Jones
--------------	-----------	------------	-------------