

## CHIRP - Bug # 7787

|   |   |                  |                   |
|---|---|------------------|-------------------|
| <b>Status:</b>  | Closed  | <b>Priority:</b> | Normal            |
| <b>Author:</b>  | Jesse Neri  | <b>Category:</b> |                   |
| <b>Created:</b>   | 04/09/2020  | <b>Assignee:</b> |                   |
| <b>Updated:</b>   | 09/23/2020  | <b>Due date:</b> |                   |
| <b>Chirp Version:</b>   | daily   |                  |                   |
| <b>Model affected:</b>  | Icom IC-92AD  |                  |                   |
| <b>Platform:</b>  | Linux   |                  |                   |
| <b>Subject:</b>   | Unable to download data from Icom IC-92AD on Linux - see also #6655 |                  |                   |
| <b>Description</b>  |   |                  |                   |
| No longer able to download data from Icom IC-92AD. Successful with Kenwood TH-D72A.                                     |   |                  |                   |
| Likely an existing problem as the last time I tried was more than a year ago. I believe this is related to Issue #6655. |   |                  |                   |
| <b>Related issues:</b>  |   |                  |                   |
| duplicates Bug # 3847: IC92AD - Errors  |   | <b>Feedback</b>  | <b>07/19/2016</b> |

### History

#### #1 - 04/09/2020 03:10 pm - Jesse Neri

Corrections to report:

Platform: Ubuntu 16.04

Model: IC-92AD

#### #2 - 05/17/2020 09:23 pm - Bernhard Hailer

- Status changed from New to Feedback
- Model affected changed from (All models) to Icom IC-92AD
- Platform changed from Windows to Linux

Applied corrections.

Question: have you also updated your Ubuntu version since you had used Chirp previously?

I'm asking because perhaps the environment for Chirp changed (port accessibility, etc.).

#### #3 - 05/18/2020 08:50 am - Jesse Neri

- File 20200518-C2-3-ChirpDaily-debug.log added
- File 20200518-C2-3-ChirpDaily-Notes.txt added

I continue to use Ubuntu 16.04. Loaded new Chirp today, problem persists. Perhaps the attached files can help. Radio Serial Number 0701402.

LSB Version:

core-9.20160110ubuntu0.2-amd64:core-9.20160110ubuntu0.2-noarch:security-9.20160110ubuntu0.2-amd64:security-9.20160110ubuntu0.2-noarch

Hi Bernhard. TU. Aiming for distribution upgrade this summer, if people using newer systems successfully connect.

#4 - 09/23/2020 06:09 pm - Bernhard Hailer

- Status changed from Feedback to Closed

Duplicates #3847. Please follow and post there. Thanks!

#### Files

---

|  |           |            |            |
|--|-----------|------------|------------|
| 20200409-C2-3-ChirpDaily-debug.log           | 2.8 MB    | 04/09/2020 | Jesse Neri |
| 20200409-C2-3-ChirpDaily-20200409-IC92AD.jpg | 161.4 kB  | 04/09/2020 | Jesse Neri |
| 20200518-C2-3-ChirpDaily-debug.log           | 1.2 MB    | 05/18/2020 | Jesse Neri |
| 20200518-C2-3-ChirpDaily-Notes.txt           | 855 Bytes | 05/18/2020 | Jesse Neri |