

CHIRP - Bug # 8277

Status:	Closed	Priority:	Normal
Author:	Brandon Boyd	Category:	
Created:	09/28/2020	Assignee:	
Updated:	09/28/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng CH-6DMR		
Platform:	Windows		
Subject:	Baofeng CH-6DMR Not Supported		
Description			
Currently no support for Baofeng CH-6DMR in latest version			
Related issues:			
duplicates New Model # 8279: Baofeng CH-6DMR		New	09/28/2020

History

#1 - 09/28/2020 05:25 pm - Bernhard Hailer

- Status changed from New to Closed

- Model affected changed from CH-6DMR to Baofeng CH-6DMR