

CHIRP - Bug # 8413

Status:	Closed	Priority:	Normal
Author:	Steven Frischling	Category:	
Created:	11/08/2020	Assignee:	
Updated:	01/31/2021	Due date:	
Chirp Version:	daily		
Model affected:	AnyTone AT-5888UV		
Platform:	MacOS		
Subject:	Anytone 5888 & CHIRP Crashing Every Single Time Its Done Reading The Radio		
Description			
<p>This evening I tried to read an Anytone 5888 a number of times with CHIRP on my Mac, and every single time it reached the end reading the brand new radio CHIRP would crash.</p> <p>I deleted CHIRP and fresh downloaded the latest version, same thing. It would read the new radio and then just crash.</p> <p>Anyone else experience this?</p> <p>Any suggestions?</p>			

History

#1 - 01/01/2021 12:02 am - Brad Schuler

Steven, Please refer to the Wiki "[[How To Report Issues]]" and provide a debug log.

#2 - 01/01/2021 04:04 pm - Bernhard Hailer

- Status changed from New to Feedback
- Priority changed from High to Normal
- Target version set to chirp-daily
- Model affected changed from Anytone 5888 to AnyTone AT-5888UV

#3 - 01/31/2021 11:51 am - Bernhard Hailer

- Status changed from Feedback to Closed

No more feedback by submitter.