

CHIRP - Bug # 8819

Status:	Closed	Priority:	Normal
Author:	JOHN STRINGER	Category:	
Created:	02/15/2021	Assignee:	
Updated:	02/18/2021	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng BF-F8HP		
Platform:	MacOS		
Subject:	Cloning Issue with February Update		
Description	<p>My BB-F8HP will no longer clone with the latest Mac OS update (chirp-unified-daily-20210212.app.zip). The transmit button is red but there is no response.</p> <p>When I open an old file and try to upload it to the radio a message at the bottom of the screen says "0 Completed Getting radio settings (idle)"</p>		

History

#1 - 02/15/2021 10:59 am - JOHN STRINGER

Issue resolved

#2 - 02/18/2021 04:19 pm - Bernhard Hailer

- Status changed from New to Closed
- Priority changed from High to Normal
- Model affected changed from (All models) to Baofeng BF-F8HP

Resolved by submitter.