

CHIRP - Bug # 9473

Status:	Closed	Priority:	Normal
Author:	Guy Immega	Category:	
Created:	10/22/2021	Assignee:	Guy Immega
Updated:	10/22/2021	Due date:	
Chirp Version:	daily		
Model affected:	Yaesu FT-70D		
Platform:	MacOS		
Subject:	Checksum error		
Description			
<p>I am running Chirp on Mac OX Mojave 10.14.6. I downloaded the latest daily version of Chirp Oct 22, 2021. I am using Yaesu USB cable.</p> <p>When I try to Download from Radio, I always get a Checksum Failed [0000-FEC9 (@FECA)].</p>			
Related issues:			
duplicated by Bug # 9471: Yaesu FT-70D checksum error		New	10/22/2021

History

#1 - 10/22/2021 02:28 am - Guy Immega

- File debug.log added

#2 - 10/22/2021 02:38 am - Guy Immega

This bug report is identical to #9471. Sorry about the duplication.

#3 - 10/22/2021 07:37 am - Jim Unroe

- Status changed from New to Closed

Closed

Files

Radio.png	62.2 kB	10/22/2021	Guy Immega
Progress Bar.png	171 kB	10/22/2021	Guy Immega
Chrip Error.png	22.5 kB	10/22/2021	Guy Immega
debug.log	499.7 kB	10/22/2021	Guy Immega