

CHIRP - Bug # 9505

Status:	Closed	Priority:	Normal
Author:	Jorge Comas	Category:	
Created:	10/30/2021	Assignee:	
Updated:	04/16/2022	Due date:	
Chirp Version:	daily		
Model affected:	Kenwood TS2000		
Platform:	All		
Subject:	No update to radio on Kenwood TS2000		
Description			
<p>Dear all,</p> <p>Please can you help me?</p> <p>After change memo file csv, it's not a avariable to upload to the radio Kenwood TS 2000.</p> <p>The Conexion on line it's ok and runnig well. I can masificate the 0-299 channels memory.</p> <p>I can save the file export to csv and recover it. But IMPOSIBLE TO UPLOAD ANY TO RADIO.</p> <p>How can I send ro the radio a csv file to upload the radio ??</p> <p>Thanks a lot in advance</p> <p>EA3HWU</p> <p>Jorge</p>			

History

#1 - 10/30/2021 10:53 am - Jim Unroe

- Status changed from New to Feedback

The Kenwood TS-2000 appears to be a live mode radio.

Since the radio is updated at the same time as changes are being made to the memories in the CHIRP spreadsheet style memory editor, there is no need to separately "upload" them. That is a process that is only necessary in "clone mode" radios.

See the CHIRP [Beginners Guide](#) for an explanation of "clone mode" and "live mode".

Jim KC9HI

#2 - 04/16/2022 05:32 am - Bernhard Hailer

- Status changed from Feedback to Closed

- Priority changed from High to Normal

- Target version deleted (chirp-daily)

- Platform changed from Windows to All

^No more traffic on this ticket.